

Quick Guide



OR-T 670

Heavy industry application
PET 25 / 32 mm







Package content








Operation




For safety regulations,
refer to operating instructions!



User interface



Cleaning/replacing wear parts



Accessories



ORGAPACK

